


Taillight with intergrated turnsignals

Suzuki C800 09-UP

Art.no.683-101

Note: Removing OEM (rear) turnsignals or change to LED, requires use of replacement Highway Hawk relay 683-2525



A: Turnsignal Left: Blue wire connect to OEM wire Turnsignal RightYellow wire connect to OEM wire

This accessory should be mounted by a professional mechanic only.

MotoLux International B.V. / Highway Hawk can not be held responsible for improper installation.

© Moto-Lux Specialties B.V. Barneveld - The Netherlands