



Note: removing OEM (rear) turnsignals or change to LED, requires use of replacement Highway Hawk relay 68-2525



- 1: Turnsignal Left : Blue wire connect to OEM wire
- 2: Turnsignal Left : Yellow wire connect to OEM wire